hadrian®

Floor toCeiling STANDARD Solid Plastic Toilet Partitions

Material Specification

<u>1.01</u> Construction

Doors, panels and pilasters shall be polyethylene solid plastic, meeting the fire test requirements of (NFPA) 286. The material shall contain no foaming agents, which can cause the formation of air pockets. The self-lubricating surface is resistant to marking and can be maintained effectively with ordinary household cleaners. Material is ideal for toilet partition installations, especially in high abuse and high moisture environments.

1.02 **Doors**

Shall be (25mm) 1" thick by (1397mm) 55" high straight cut with fine radius edges.

1.03 Panels

Shall be (25mm) 1" thick by (1397mm) 55" high straight cut with fine radius edges.

<u>1.04</u> Pilasters

Shall be (25mm) 1" thick and straight cut with fine radius edges.

<u>1.05</u> Pilaster Fastening Method

Pilasters shall be securely and rigidly fastened to structural steel or pre-cast concrete supporting member in the ceiling (note: wood support is not acceptable) by means of two heavy hanging studs permitting vertical adjustment between bottom of supporting member and finished ceiling line. Heavy hanging studs to be attached to pilasters by means of a heavy duty, 3/8" (10mm) thick mounting bracket. Hadrian supplied ceiling studs MUST be used to create a secure installation. Pilasters shall be fastened to the floor on vertically adjustable floor brackets. Floor and ceiling connections shall be concealed and protected by a 4" (102mm) high stainless steel sleeve pilaster shoe.

Note: This specification does not include the supplying, installing, drilling or tapping of any of the structural members required in the ceiling for support of these units. Only the stude are supplied for installation by others.

<u>1.06</u> Hardware & Fittings

Doors are installed with 1/8-inch (3 mm) thick extruded clear anodized, 8 inch (203 mm) rounded aluminum hinges, which wrap around both the door and pilaster. Hinges shall be fastened to door and pilaster with tamper-proof 6-lobe security head stainless steel thru-bolts and to the edge of door and pilaster with #10 by 1-inch (25 mm) screw. Top hinges shall have adjustable nylon cams. Strike-keeper and throw latch shall be of extruded clear anodized aluminum. Three heavy-duty aluminum brackets are used at the panel to wall connection and a full-height continuous aluminum channel is used at the panel to pilaster connection. Inswing doors shall be fitted with a zinc die cast, #4 brushed combined coat hook and bumper. Outswing doors shall be fitted with a #4 brushed stainless steel flat coat hook. Fasteners are theft-proof 6-lobe security head stainless steel screws.

1.07 Finish

Doors, panels and pilasters shall be polyethylene solid plastic with uniform color throughout. Color shall be as selected from Hadrian's NFPA 286 color offerings.




 Hadrian Manufacturing Inc.,
 965 Syscon Road, Burlington, ON, Canada, L7L 5S3
 • Tel: (905) 333-0300
 • Fax: (905) 333-1841

 Hadrian Inc.,
 7420 Clover Avenue, Mentor, OH, U.S.A., 44060
 • Tel: (440) 942-9118
 • Fax: (440) 942-9618

 www.hadrian-inc.com
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •
 •

hadrian

Floor toCeiling **STANDARD Solid Plastic Toilet Partitions**



plan detail A-A

Important Notes:

Structural steel or pre-cast concrete required as support in ceiling.

Structural support and drilling for studs by others. Studs available from Hadrian but installed by others.

Refer to final drawings for wood blocking information. Wood blocking is critical to ensure a rigid installation. Hadrian supplied ceiling studs MUST be used to create a secure installation.



Hadrian Manufacturing Inc., • Fax: (905) 333-1841 965 Syscon Road, Burlington, ON, Canada, L7L 5S3 • Tel: (905) 333-0300 Hadrian Inc. 7420 Clover Avenue, Mentor, OH, U.S.A., 44060 • Tel: (440) 942-9118 • Fax: (440) 942-9618